

Safety Management System (HSG65)

Audit and Premises
Inspection Report
2024-2025

Bradshaw Hall Primary



Stockport Metropolitan Borough Council Health, Safety & Wellbeing Department Stopford House Piccadilly Stockport SK1 3XE

1. Document Control

| Audit & Inspection of: | Bradshaw Hall Primary School Vernon C8 6ANlose Cheadle Hulme |
|--------------------------|---|
| | Stockport SK8 6AN. |
| Audit & Inspection by: | Sue Pullan, Health, Safety, and Wellbeing Team SMBC, Chris Bagnall Headteacher, Richard Gleaves, School Health and Safety Officer, and Jason Preston, Site Manager. |
| Audit & Inspection date: | 10 th October 2024 |
| Reference: | HSW/A&IR/SP/008 |

| DOCUMENT DETAILS | |
|--------------------|--|
| Document Title: | Safety Management System Audit and Inspection Report |
| Document Owner(s): | Health, Safety and Wellbeing Team |
| Version Number: | Version 1.0 |
| Document Status: | Live |
| Document Date: | 14 th October 2024 |

| REVISIO | REVISION HISTORY | | | |
|---------|------------------|--------|-----------|-------------------------------|
| Version | Status | Author | Date | Notes |
| 1.0 | DRAFT | | | |
| 2.0 | Live | | 14.10.24. | Report sent out to the school |

SCHOOL SIGNATURES – To be signed off post audit The OSHW arrangements are reviewed annually to ensure that policies and procedures documented remain up to date and relevant. Headteacher signature: Date:

2. Contents

| 1. | Document Control | 1 |
|----|---|----|
| 2. | Contents | |
| 3. | Disclaimer | |
| 4. | Introduction | |
| 5. | Acknowledgements | 4 |
| 6. | Background | 4 |
| 7. | Aims and objectives | 4 |
| 8. | Methodology | 4 |
| 9. | Findings of the Audit | 5 |
| 10 | | 5 |
| | Occupational Health Safety and Welfare (OHSW) Policy | 5 |
| | Risk Assessments | |
| | Safe Systems of Work (SSoW) | 7 |
| | Working at Height | 8 |
| | Manual Handling | |
| | Control of Substances Hazardous to Health (CoSHH) | |
| | Dealing with Accidents, Incidents and III-Health and First Aid | 11 |
| | Communication, Consultation and Cooperation | 12 |
| | Business Continuity (Including Critical Incident Management and Lockdown) | 13 |
| 10 | .2 Buildings and Grounds | 14 |
| | Fire Safety Management | 14 |
| | Asbestos | 16 |
| | Legionella Risk Assessment | 16 |
| | Gas and Electrical Safety: Systems and Appliances | 18 |
| | Outdoor Play Equipment | 18 |
| | Contractors | |
| | Pedestrian and Vehicular Movement | |
| | Kitchen: Access | 19 |
| | Kitchen: Extractor Hoods | 19 |
| | Stage Lighting and Rigging | |
| | Roller Shutters | 20 |
| | Gates and Barriers | |
| | Air Conditioning Units | |
| | LOLER Inspections | |
| 10 | .3 High Risk Curriculum Areas and Staff Training | 21 |
| | Science | |
| | Physical Education: Equipment | |
| | Physical Education: Storage | |
| | Design and Technology | |
| | Health and Safety Training: Induction Training | |
| | General health and safety training | |
| 10 | .4 Performance Monitoring and Measurement | 23 |
| | Active Monitoring | |
| | Reactive Monitoring | 24 |
| 10 | .5 Audit | 24 |
| | Auditing and Reviewing the OHSWMS | |
| | .6 Statutory Compliance Checklist | 25 |
| | .7 Physical Inspection – Observations and Recommendations | 29 |
| | Guidance to school | |
| | Executive Summary | |
| 12 | Inspection and Audit Action Plan | 32 |

3. Disclaimer

Every effort has been made to ensure that all statements and information offered in this report are accurate and true and are related to or qualified by observations made during the audit and inspection, together with information supplied by the school.

In the time available, the audit did not confirm every activity affecting the school, although every effort has been made to identify a realistic picture.

This report only comments on the conditions observed, information supplied, and impressions gained at the time of the visit; it should not be taken as identifying all aspects of possible unsafe conditions and/or contravention of statutory requirements.

The accuracy of this audit report rests on the representations made by the school being honest and truthful. The organisation must therefore notify Stockport Metropolitan Borough Council (SMBC) of any factual inaccuracies or misinterpretations of information provided by the organisation as reflected in this report.

NB: Please note that this audit and inspection report represents a snapshot in time completed by an individual SMBC Audit Officer. Due to differences in knowledge, experience, and skills consequently officers will not always the same faults or issues.

4. Introduction

As part of Stockport Metropolitan Borough Council's Occupational Health, Safety, and Welfare (OHSW) monitoring process, your school has recently been through an OHSW audit and inspection.

The audit was conducted by reviewing the school's health and safety documentation and procedures. This was accompanied by an inspection or tour of the site and associated buildings.

The audit and inspection are tools used to determine the effective implementation of the school's OHSW standards. This report has been prepared to identify the strengths and weaknesses in your Occupational Health, Safety, and Welfare Management System (OHSWMS). It provides recommendations for consideration, giving a basis from which continuous improvements to the standards of health, safety, and welfare can be made.

The purpose of this report is to provide the school's leadership team and governing body with an assessment of the effectiveness of the school's health and safety management provisions. Although it would also be useful to share the report with staff and parents/carers as part of the school's ongoing engagement with health, safety, and welfare issues.

The report serves to highlight strengths and describe weaknesses in the school's management of occupational safety, health, and welfare and recommends solutions and timeframes for resolutions where deficiencies and issues are identified.

The report focuses on areas of significant quality management and highlights areas that require improvement. It is felt that this qualitative approach will help schools grow stronger in the four management categories of plan, do, check, and act, which form the basis of the SMBC OHSWMS.

5. Acknowledgements

The auditor would like to place on record thanks to all staff who gave their time and assisted with the audit process.

Thanks go to the headteacher, health and safety officer, and the site manager for their precious time and hospitality at the audit.

6. Background

According to both the school's and the authority's records, this is the 8th formal audit and inspection of the school's OHSWMS since these audits began in 2015.

7. Aims, and objectives.

The primary aim of this audit and inspection is to provide an external and independent assessment of the OHSWMS and arrangements developed by the school and the effectiveness of their implementation.

8. Methodology

The audit and inspection were carried out in two parts:

- 1) A desktop audit of the school's health and safety management system.
- 2) A physical inspection of the school's premises.

During both activities, the auditor gathered evidence of the school's approach to safety management by:

- a) Comprehensively reviewing safety management documents to check for: suitability and sufficiency and regular review and revision
- b) Asking questions of key staff to check for an awareness and understanding of workplace health, safety, and wellbeing provisions
- c) Touring the workplace to check for a clean, tidy, healthy, and safe work environment and to observe work processes and safe systems of work to see whether procedures are followed and ensure that appropriate measures are in place to control hazards and mitigate risk.
- d) The audit and inspection have five distinct components:
 - (i) Policies, procedures, risk assessments, safe systems of work and communication
 - (ii) Buildings, facilities, and grounds
 - (iii) High risk curriculum areas (e.g., PE and forest schools) and staff training
 - (iv) Performance monitoring and measurement
 - (v) Audit

The results from the above components combine to produce the inspection and audit action plan.

9. Findings of the Audit

10.1 Policies, Procedures, Risk Assessments, Safe Systems of Work and Communication

| Occupational Health Safety and Welfare (OHSW) Policy | What we found during the audit |
|---|--|
| To comply with the law, the school should have an OHSW (Occupational Health, Safety, and Welfare) plan that makes clear the organisational structure and arrangements for managing health, safety, and welfare. | The Health and Safety Policy was dated September 2023 and contained all of the appropriate |
| The OHSW policy should describe in detail the responsibilities and expectations of workers and managers, making it clear that performance will be monitored, and people held accountable. | information that is required within a health and safety policy. |

BEST PRACTICE:

The OHSW policy should inform staff, on a practical level, of how they are expected to fulfil specific duties in accordance with the "school procedures and rules". The OSHW policy should be amended, therefore, when a significant change occurs, for example changes in workplace practices and procedures

WHAT THE LAW SAYS:

The OHSW policy should be consulted on with staff and Union representatives where possible and once it has been signed off by governors, it must be effectively communicated to all staff. This could be done for example, by letting the staff know that it is available on the shared drive or staff health and safety notice board.

LEGAL REFERENCE(S)

The Health and Safety at Work Act 1974, Section 2 (3)

'it shall be the duty of every employer to prepare and as often as may be appropriate revise a written statement of... general policy... and to bring the statement and any revision of it to the notice of all employees.'

Furthermore, **Section 2 (6)** outlines "the duty of every employer to consult on any such arrangements with a view to the making and maintenance of arrangements..."

FURTHER INFORMATION:

It is recommended that the OSHW arrangements be reviewed annually to ensure that procedures documented remain up to date and relevant.

Following this review, the headteacher and chair of governors must sign the policy.

| Risk Assessments | What we found during the audit |
|---|---|
| To comply with the law, all significant risks must be identified, and a well-developed system for identifying hazards and evaluating risks relating to worker safety and health should be in place. Preventative and protective measures must be in operation, and the hierarchy of controls must always be observed. Site-specific, generic, and risk assessments for trips must be in place, and there must be evidence that these are reviewed on a regular basis and that they give an accurate reflection of the risks and the control measures in place at the school. Examples of Risk assessments that should be completed are: Opening and closing site Snow clearance/gritting Office Trolley General cleaning | Risk Assessments were viewed at the audit and, had been reviewed in |
| Office Trolley | |
| Hand- held tools. Short use of stepladders Use of pressure washer | |
| This list is not exhaustive | |

BEST PRACTICE:

Examples of suitable and sufficient risk assessments are available from the Health, Safety and Wellbeing team on request. These are meant as guides only and provide a good indication of the hazards found in most schools. Any specific risk assessment MUST be modified to accurately reflect the hazards found in your own school and the control measures that you have in place.

WHAT THE LAW SAYS:

There is a legal obligation to record the control measures in place, and as such, care should be taken to ensure that risk assessments are relevant, in every detail, to the activity or area being assessed. Written risk assessments and the associated control measures must be reviewed regularly. SMBC recommends that this is done annually or if there has been a significant change to working operations or practices.

It is a legal requirement for every employer to assess the health and safety risks arising out of their work under regulation 3 of the Management of Health and Safety at Work Regulations 1999.

This means to assess the significant risks and to put into place suitable and sufficient control measures. In addition, there is a requirement to consult staff in this process and effectively communicate the findings of these assessments to them. Once in place, the risk assessments must be monitored and reviewed to ensure that they remain relevant. Risk assessments must be reviewed regularly, following an accident, and to reflect changes within the school, e.g. the introduction of new equipment, substance, change in policy/procedures, a change in legislation or advancement in technology, etc. Staff should be involved in this process.

Safe Systems of Work (SSoW)

To fully comply, a well-documented array of information should be maintained in the form of safe work systems and school operating procedures (for example, working at heights and opening and closing the school or academy).

Comprehensive and robust arrangements should exist for prevention, preparedness, and response to accidents and incidents, and these must be regularly maintained and tested. There should be good awareness of the arrangements amongst staff.

Individual and specific events should be analysed, and where necessary safe systems of work have been put in place.

Please contact the Health, Safety, and Wellbeing Team if you need help developing your Safe System of Work.

What we found during the audit

The school has a robust system in place for ensuring that safe systems of work are in place and followed. All arrangements are comprehensive and shared with appropriate staff members.

All staff have access to shared documents through the school's online system.

The school sends in their trip risk assessments to SMBC HSW, where they are reviewed.

Accidents and incidents are reported in house, and, where required reported to SMBC HSW on the SMBC accident/incident reporting system.

WHAT THE LAW SAYS:

The Management of Health and Safety at Work Regulations 1999, Regulation 3 (4)

'Any assessment such as is referred to in paragraph (1) or (2) shall be reviewed by the employer or self-employed person who made it if a) there is reason to suspect that it is no longer valid; or b) there has been a significant change in the matters to which it relates; and whereas a result of any such review changes to an assessment are required, the employer or self-employed person concerned shall make them

The Health and Safety at Work Act 1974, Section 2 (2) (a)

An employer has the duty for '...the provision and maintenance of plant and systems of work that are, so far as is reasonably practicable, safe and without risks to health...

The Management of Health and Safety at Work Regulations 1999, Regulation 8 (1)

'Every employer shall a) Establish and where necessary give effect to appropriate procedures to be followed in the event of serious and imminent danger to persons at work in his undertaking..."

Working at Height

To comply, a robust policy (using the hierarchy of control: avoid, prevent, and minimise) must exist for all workers working from heights. All ladder work lasting less than 30 minutes must be competency-based, and risk assessed.

Any activity that lasts longer than 30 minutes must have a full and considered risk assessment. Caretaker's ladders should be subject to a six-monthly visual and recorded inspection by the caretaker.

Duty holders (head teachers) must do all that is reasonably practical to prevent anyone falling from heights or from a level surface to a depth, which are liable to cause injury.

The key responsibilities of the Duty Holder are to ensure that:

- All work at height is properly planned and organised.
- The place where work at height is carried out is safe.
- The equipment for work at height is appropriately inspected and maintained.
- All work at height is carried out in a safe manner, using appropriate work equipment.
- All persons involved in working at height are suitably trained, competent, and are supervised appropriately.
- Supervision should be carried out by a competent person
- The risks arising from fragile surfaces are properly controlled.

The risks arising from falling objects are properly controlled.

What we found during the audit

The Working at Height Risk Assessment was up to date.

If ladders are to be used, they are visually inspected. Ladder Inspections take place on a quarterly basis.

The school are looking at introducing a tag system for ladder inspections.

The Site Team do not access the roof at any time. Any roof work is carried out by contractors.

FURTHER INFORMATION:

A copy of the SMBC Guidance for Working at Height Policy is available from the Health, Safety and Wellbeing Team. HRSafety&HealthTeam@stockport.gov.uk

Manual Handling What we found during the audit All significant examples of manual handling must be risk assessed and these risks assessments regularly reviewed. Staff who require training have been identified and receive training and instruction. SMBC adheres to the **SMART** approach to lifting: Size up that load. Assess the load (shape, size, and weight) Determine where the load needs to be moved and A Manual Handling Risk Determine whether you can carry the load/whether Assessment is in place and followed a mechanical aid should be used. by staff members. Move the load as close to the body as possible. Carry the load as close to the body as possible. Manual Handling Training has been Secure your grip. undertaken by key staff who carry Always bend your knees out any tasks/activities that may Keep feet apart in a comfortable position (usually include manual handling. Manual in line with hips) handling training is refreshed every 3 years. Minimise lower back bending. • Bend knees (squat or semi-squat position) Raise the load with your legs. Lift the load with your legs, not your back, in a smooth motion (avoid twisting or jerky movements) Maintain normal curvature of the spine. Turn your feet in the direction you want to move. Change direction by pointing your feet and not twisting your back. To set the load down, squat down, keep your head up and allow your legs to carry the weight.

Please note that manual handling training is provided by the Health, Safety and Wellbeing Team at SMBC and can be booked through SLA Online; https://secure2.sla-online.co.uk/SelectPortal.aspx

Control of Substances Hazardous to Health What we found during the audit (CoSHH) To fully comply product safety data sheets should be COSHH Assessments are in place and obtained from the manufacturer for every substance were, up to date. COSHH Assessments used at the school. COSHH risk assessments must are reviewed on an annual basis. be completed for all products used in the school and available for inspection in the Fire information file for Safety Data Sheets are in place to go the Fire and Rescue Service which is kept in the main alongside the COSHH Assessments. office. A copy of COSHH risk assessment should also be kept in the caretakers/site manager's office Staff members are aware of the need to with the associated product for ease of access let the leadership team know of any especially during emergency situations. allergies they suffer so that appropriate products are used on site. COSHH risk assessments should be completed for substances used in the following departments: Site Manager Kitchen

Design and Technology Areas

The school currently use 6 cleaning products on site.

This list is not exhaustive.

Chemical Storage

To fully comply hazardous substances must be stored correctly. Hazardous substances should be kept to a minimum and always replaced with less harmful products where possible.

Flammable substances must be kept securely in a fireretardant cupboard with suitable ventilation and away from ignition sources. Steps must be taken to ensure appropriate separation of hazardous substances to guard against accidental mixing. Pupils must not be granted unsupervised access to hazardous substances at any time. All products on site were appropriately stored behind secured and locked areas.

Pupils do not access the chemical storage areas

If a container shows a warning symbol (see examples below), you must assess the risks to users.



WHAT THE LAW SAYS:

The Control of Substances Hazardous to Health (COSHH) Regulations stipulates that employers must:

- assess the risks to health from chemicals and decide what controls are needed.
- use those controls and make sure workers use them.
- make sure the controls are working properly.
- inform workers about the risks to their health; provide training for employees.

Safety data sheets and/or COSHH risk assessments should be made available for users of hazardous substances.

The Dangerous Substances and Explosive Atmospheres Regulations, 2002 require that flammable and highly flammable substances be controlled. These include petrol, LPG, solvent-based paints, varnishes, and some types of dust.

BEST PRACTICE:

Butane (blue cylinders) and propane (red cylinders) both of which can be used for running domestic type BBQ's used at school fairs/fates should not be stored on school premises. Any solvent-based products should be stored in lockable metal containers

FURTHER INFORMATION:

Regarding the control of hazardous substances can be obtained from www.hse.gov.uk/COSHH/index.htm and a COSHH assessment tool is available from www.coshh-essentials.org.uk.

Help and advice is also available from the Health, Safety and Wellbeing team at the Council: HRSafety&HealthTeam@stockport.gov.uk

| Dealing with Accidents, Incidents and III-Health and First Aid | What we found during the audit |
|---|--|
| ACCIDENT RECORDING: | |
| The school should be using the SMBC portal below to report accident injuries and dangerous occurrences https://forms.stockport.gov.uk/accidents-and-incidents/what-are-you-reporting | The school have appropriate accident/incident reporting procedures in place. |
| and use the portal to report and record the more serious incidents and especially where incidents involve a "workplace activity", school facilities or equipment. Cuts, grazes, and bumps should be managed appropriately via a locally held accident reporting system based at the school. | Any serious accidents are reported to SMBC through the on-line Accident/Incident Reporting System. |
| ACCIDENT REPORTING | |
| Staff should be aware of the procedures for reporting incidents as required under the 'Reporting of injuries, diseases, and dangerous occurrences regulations (RIDDOR) and should be able to properly identify accidents and incidents which must be highlighted to the Health, Safety and Wellbeing Team at SMBC for reporting to the Health and Safety Executive. | RIDDOR Reportable accidents are reported to the HSE by SMBC with copies sent to the school for their records. |
| ACCIDENT/INCIDENT INVESTIGATION AND | |
| MONITORING The school should maintain a well-documented recording system to track and document accidents and incidents. The recording of information complies with the law and provides a basis for effective analysis. It is recommended that an overview of accidents/incidents be regularly provided to the Head Teacher and Governing body so that trends can be monitored. | The school has a sufficient accident investigation procedure in place with trend analysis in place. |
| FIRST AID PROVISION (Including early years up to 5 | |
| years old where applicable) In order, to comply the school must provide well- resourced first aid arrangements in terms of trained | The school have an adequate number of trained first aiders on site. |
| personnel and equipment. It is a requirement of the statutory framework that a paediatric first aider is always on school premises when children are present (and at least one person with paediatric first aid on outings) | The school do have residentials in place, where the venue staff are fully first aid trained. Staff who attend the trips are also trained first aiders. |
| FIRST AID RECORDS In addition to recording more serious incidents, minor injuries and any first aid treatment given is locally recorded. During the audit, evidence was produced to show that any first aid treatment given is properly recorded. | First aid records were in place and, are appropriately recorded. |
| ADMINISTRATION OF MEDICINES The school must have procedures in place to support pupils with health and medical needs. These include a written parental request form, a monitoring system and secure storage for medicines. Staff should be | Staff follow the Administration of Medicines Policy. They sign to say that they have read and understand the policy. |
| secure storage for medicines. Staff should be designated to administer medical care as and when required, ensuring each dosage is properly logged to avoid an accidental overdose. | If any wrongful administration were to occur this would be reported to SMBC HSW via the on-line accident/incident reporting system. |
| BEST PRACTICE: | |

BEST PRACTICE:

The Information Management Toolkit for Schools (IRMS) is designed as guidance and sets out certain requirements for the keeping of records.

- For accidents involving adults in schools, it is the date of the accident + 6 years.
- For accidents involving pupils it is the Date of Birth + 25 years
- Records relating to serious accidents and injury should be kept for date of incident + 12 years.

WHAT THE LAW SAYS:

The Management of Health and Safety at Work Regulations 1999, Regulation 8 (1) 'Every employer shall—

Establish and where necessary give effect to appropriate procedures to be followed in the event of serious and imminent danger to persons at work in his undertaking...'

The Health and Safety (First Aid) Regulations 1981, Regulation 3

- '(1) An employer shall provide, or ensure that there are provided, such equipment and facilities as are adequate and appropriate in the circumstances for enabling first-aid to be rendered to his employees if they are injured or become ill at work.
- (2) Subject to paragraphs (3) and (4), an employer shall provide, or ensure that there is provided, such number of suitable persons as is adequate and appropriate in the circumstances for rendering first-aid to his employees if they are injured or become ill at work; and for this purpose, a person shall not be suitable unless he has undergone:
 - a) such training and has such qualification as the Health and Safety Executive may approve for the time being in respect of that case or class of case, and
 - b) such additional training, if any, as may be appropriate in the circumstances of that case.'

The Social Security (Claims and Payments) Regulations 1979, Regulations 25 (3)

'...every employer by whom 10 or more people are normally employed... shall, subject to the following provisions of this paragraph –

Keep readily accessible a book... in which the appropriate particulars... of any accident- causing personal injury to a person employed by the employer...

Communication, Consultation and Cooperation

Communication, consultation, and cooperation are all essential elements of a robust health and safety ethos and are a legal requirement under the Management of Health and Safety at Work Regulations 1999.

Staff should be provided with health and safety information and be able to raise any health and safety concerns directly to the head, the site manager or caretaker, and their line manager.

Additional health, safety, and wellbeing information should be provided to staff by the staff handbook, the health, safety, and wellbeing notice board, and regular items on staff and governors meetings.

What we found during the audit

Effective communication is fed down from SLT to front line staff.

The staff room houses a Health, Safety, and Wellbeing Notice Board with appropriate information installed on it

There is a staff handbook in place. Staff are aware of monthly health and safety meetings taking place on site. Appropriate records are kept.

The Full Governing Board have health and safety as a standing item.

BEST PRACTICE:

Good communication of, health and safety, can be achieved by a number, of ways. Staff can be provided with health and safety information through:

- Staff meetings
- Departmental meetings
- Health and safety committees
- Leadership groups

There should be a clearly defined route through which staff can express health and safety concerns. Staff should feel confident that their concerns are dealt with and so ideally such suggestions should be recorded.

The staff handbook is a useful way to communicate health and safety procedures. This could be located on the staff shared drive and should include information on how staff can report health and

safety concerns, how staff should report defects, risk assessments, emergency procedures, accident reporting and how staff can access health and safety related policies and procedures.

ISO45001 Clauses 7.4.1 to 7.4.3

"The organisation must establish, implement and maintain a process or processes for internal and external communications relevant to the OH&S management system, which provides for the gathering, updating and dissemination of information and which encompasses the following: What topics to communicate on, when to communicate, with whom to communicate, how to communicate".

It is, therefore, a legal requirement to consult and communicate with employees in all aspects of health and safety provision within the school and is an essential element of creating a robust health and safety culture.

Employers have a duty to consult with their employees, or their representatives, on health and safety matters. Union safety representatives or employee safety representatives can assist with this process as well as providing valuable guidance in health and safety matters.

WHAT THE LAW SAYS:

It is a requirement that employers must consult all their employees on health and safety matters about:

- i). the introduction of any measure which may substantially affect their health and safety, e.g., the introduction of new equipment or new systems of work.
- ii). the arrangements for getting competent people to help them comply with health and safety laws.
- iii). the risks that have been identified from risk assessments, the hazards and dangers employees will be exposed to, and the measures in place to reduce or remove the risks.
- iv). the planning and organisation of any health and safety training
- v). the health and safety consequences of introducing new technology.

Business Continuity (Including Critical Incident What we found during the audit **Management and Lockdown)** An emergency plan must be prepared so that staff are aware of the procedures to follow in a crisis. It is good practice to formally set out actions to be taken by designated staff during an emergency. The plan should cover minor incidents (e.g., heating breakdown, no water, etc.), when the school may have to close for a short time, A Business Continuity Plan is in and major incidents (e.g., fire, fatality, etc.), which may place and, was up to date. cause major disruption to the school. The emergency plan must include details of how the school will manage Emergency procedures were in the dismissal of children and the collection arrangements place. for parents and carers. There is a Lockdown Policy in place Consideration should be given to including the following which is also up to date. in the plan: The last Lockdown test was undertaken in December 2023. How to respond efficiently during a crisis Lockdown tests are carried out safeguarding pupils, staff, and visitors, this should name individuals and their roles during the biannually. There is a lockdown policy with preventing an escalation of the situation lockdown procedures incorporated Arrangements to temporarily relocate pupils if necessary. into it. Contact details, e.g., emergency numbers, school services, critical incident response teams, etc. Emergency arrangements in case of an incident during an educational visit.

Once the emergency plan has been ratified by the governing body, it should be shared with all those with responsibilities so that they are aware of the procedures to follow in a crisis. SMBC is, able to provide advice in relation to emergency planning. For further details, contact samantha.jones@stockport.gov.uk

The first step in preparing a lockdown policy is to be realistic about the risks to the school and its pupils, which will be linked to the ease of access into the school buildings. While terrorism has prompted schools to consider a lockdown procedure, different schools will identify different risks, and the likelihood of a negative event will vary. The risk may come from an intruder, an aggrieved parent, or an incident in the immediate vicinity of the school.

A written lockdown plan must be in place and have been signed off on by the governors. The lockdown procedure should be tested at least twice per year in, order to ensure that staff and pupils are familiar with the requirements.

The lockdown plan should include the notification process for a return to normal. Drills and practises should be recorded, and lessons learned should be observed and used to improve the plan when it is reviewed annually.

10.2 Buildings and Grounds

Fire Safety Management

FIRE RISK ASSESSMENT

The school must have an up-to-date fire risk assessment in place, which must be suitable and sufficient meaning that the main risks have been identified within the facilities.

All actions must be worked through, and recommendations implemented. See table below for dates and provider.

What we found during the audit

The Fire Risk Assessment was dated 28.5.24 and had been carried out by Firesec. Actions from the fire risk assessment have been prioritised, and actioned, where appropriate. The school are currently working through actions raised within their fire risk assessment. The Fire Risk Assessment is reviewed annually by the leadership team.

WHAT THE LAW SAYS:

Under The Regulatory Reform (Fire Safety) 2005 Order every premises with 5 or more employees must assess the risks from fire, record the findings and inform all staff of the outcome of the assessment.

BEST PRACTICE:

It is recommended by SMBC that 4 years is the maximum period that should be left between Fire Risk Assessments.

FIRE ALARM – TESTING AND MAINTENANCE BY A COMPETENT PERSON

The fire alarm must have serviced within the last 6 to 12 months and service records available to evidence this – see table below.

Firequeen last serviced the fire alarm on 5.6.24.

EMERGENCY LIGHTING TESTING AND MAINTENANCE BY A COMPETENT PERSON

The emergency lighting must have been serviced within the last 6 to 12 months and service records available to evidence this. See table below. Firequeen last serviced the emergency lighting on 5.6.24.

FIRE-FIGHTING EQUIPMENT – SERVICE BY A COMPETENT PERSON

Fire-fighting equipment must have been serviced in the last 12 months and service records available to evidence this. See table below.

The fire-fighting equipment was last serviced on 15.1.24 by Firequeen.

CALL POINTS - CHECKS BY THE SCHOOL

A different call point should be tested weekly, and the results recorded. The Fire Authority will ask to see evidence that these tests are carried out when the school is inspected. Failure to produce written evidence could result in an improvement notice. It is an offence to falsify records. See table below.

The call points are checked by the site manager every week and are documented on the weekly checklist. The last documented date was 8.10.24.

EMERGENCY LIGHTING – CHECKS BY THE SCHOOL Emergency lights must be tested monthly. See table below.

Emergency lighting is checked on a weekly basis by the site manager and the last documented date was 8.10.24.

WHAT THE LAW SAYS:

All emergency lights must be checked each month to ensure continued operation of all assets. Results should be recorded, and faults rectified immediately.

MEANS OF ESCAPE - CHECKS BY THE SCHOOL

The school must check the facilities, equipment, and devices (e.g., fire exits, fire doors, exit routes) provided for fire safety on a weekly basis for damage, blockages, and ease of access. A written record of these checks should be kept. See table below.

The means of escape are checked on a weekly basis. The last documented date was 8.10.24 and was carried out by the site manager.

WHAT THE LAW SAYS:

It is a legal requirement to ensure that facilities, equipment, and devices provided for fire safety are checked on a weekly basis. For example, that emergency exit routes are not blocked, that final exit routes and stairwells are free from combustible material and that fire doors are in good working order. Regular checks must be included in an effective fire prevention monitoring routine.

FIRE DRILLS

Timed emergency evacuation drills must be carried out each term and properly recorded. See table below.

The last Fire Drill was conducted on 17.9.24 with documented records kept.

BEST PRACTICE:

Guidance in relation to the display of pupil's work in in accordance with the Fire and Regulatory Reform Order 2005 and as agreed by OFSTED, Chief Fire Officers Association and the Department for Education is available from the health, safety and wellbeing team on request. HRSafety&HealthTeam@stockport.gov.uk

| Asbestos | What we found during the audit |
|--|--|
| An up-to-date management survey of Asbestos Containing Materials (ACMs) must be held by the school, and the risks associated with these ACMs must be assessed. The survey should be updated annually to reflect changes in circumstances and the condition of the asbestos. A plan must exist for the management of the asbestos in the school. | A Full Asbestos Management Survey of the whole school was last conducted in 2021. |
| Staff and visitors to the school (especially contractors) must be made aware of the location of any asbestos and understand the risks involved in any accidental disturbance. The management of asbestos must be kept under review and be reported to the governors at least annually or when any refurbishment work is due to take place in the school. | The last documented Asbestos Audit Report date was 3.10.24 and had been undertaken by Mark Hall from Robertson's facilities management. The Asbestos Register was last updated in 2024. |
| There is a legal duty to ensure that: Staff and contractors are made aware of the location and type of ACM. The state of the ACMs is monitored, and changes in condition are reported immediately. | An Asbestos Policy was in place and was dated 2022. Policies are reviewed annually. Asbestos Awareness Training has been undertaken by key staff. |
| The survey and risk register are updated following the removal of any ACMs by a competent person. | |

WHAT THE LAW SAYS

The Control of Asbestos Regulations 2012 states:

"The measures to be specified in the plan for managing the risk shall include adequate measures for

- a) monitoring the condition of any asbestos or any substance containing or suspected of containing asbestos.
- b) ensuring any asbestos or any such substance is properly maintained or where necessary safely removed; and
- c) ensuring that information about the location and condition of any asbestos or any such substance is:
 - (i) provided to every person liable to disturb it
 - (ii) made available to the emergency services."

| Legionella Risk Assessment | What we found during the audit |
|--|----------------------------------|
| It is a legal requirement to have up to date versions of | The Legionella Risk Assessment |
| the following two documents available for inspection on | and Written Scheme of Work was |
| site at any time: | dated 20.10.23. and had been |
| A Legionella Risk Assessment (LRA) | undertaken by Acorn Environment |
| 2. A Written Scheme of Works (sometimes called a | Management. |
| Written Scheme of Control) | |
| These documents must have been completed by a | |
| competent person. | Monthly water temperatures are |
| | undertaken by Acorn Environment. |
| Concerns raised in the risk assessment must have been | The last documented date was |
| addressed and the school should have received a | 18.9.24 |

prioritised list and explanation of what work is required and why.

It is recommended that weekly temperature tests as recommended by the legionella risk assessment should be carried out by the site manager, who must have received the necessary training.

Further advice is available on the management of Legionella from your service provider and via SLA online. Weekly water temperatures are undertaken by key staff. The last documented date was 8.10.24.

Weekly flushing of little used outlets is carried out by the site team. The last documented date was 8.10.24.

WHAT THE LAW SAYS:

Extracts below taken from L8 (Fourth edition) Published 2013

Legionella Risk Assessment

- 47. The record of the assessment is a living document that must be reviewed to ensure it remains up to date. Arrange to review the assessment regularly and specifically whenever there is reason to suspect it is no longer valid. An indication of when to review the assessment and what to consider should be recorded. This may result from, e.g.:
- (a) changes to the water system or its use
- (b) changes to the use of the building in which the water system is installed
- (c) the availability of new information about risks or control measures
- (d) the results of checks indicating that control measures are no longer effective
- (e) changes to key personnel
- (f) a case of legionnaires' disease/legionellosis associated with the system

Written Scheme of Works

- 65. For precautions to remain effective, the condition and performance of the system will need to be monitored. The appointed responsible person should oversee and manage this. Or, where appropriate, an external contractor or an independent third party can do it. Management should involve:
- (a) checking the performance and operation of the system and its component parts
- (b) inspecting the accessible parts of the system for damage and signs of contamination
- (c) monitoring to ensure that the treatment regime continues to control to the required standard.
- 66. The frequency and extent of routine monitoring will depend on the operating characteristics of the water system.

Advice should be taken from competent service providers on the frequency of the Risk Assessment and the Written Scheme of Control.

| Gas and Electrical Safety: Systems and Appliances | What we found during the audit |
|--|---|
| GAS SAFETY Service records should be available to show that the gas boilers are serviced regularly, See table below. | Gas Soundness checks were last undertaken on 11.10.23. Gas Boilers were last serviced on 28.6.24 by the Dodd Group. Gas Appliances were last serviced on 28.6.24. Gas Pressure Vessels will form part of an annual service check. |
| FIXED ELECTRICAL INSTALLATION A competent person should have checked the fixed electrical installations within the last 5 years and documentation provided to evidence this. Failed installations and other C1 and C2 recommendations should have been acted upon. See table below. | The last 5-yearly fixed electrical installation service was carried out on 7.8.19. The whole school has benefitted from being rewired during 2022. |
| PORTABLE ELECTRICAL APPLIANCES The school has a suitable and sufficient PAT policy in place (including a risk assessment) and any equipment identified as high risk in this assessment has been tested. Further information and full suite of management documentation is available on SLA online. See table below. | PAT Testing was last carried out on 13.2.24 by Bradbell. |

| Outdoor Play Equipment | What we found during the audit |
|---|--|
| As part of best practice, a formal prior to use inspection of the playground equipment should be carried out daily by supervising staff. Monthly recorded inspections should be undertaken and recorded by a competent person (Site Supervisor) and records available to verify this. Additionally, an annual inspection by an insurance approved contractor should be carried out. Any issues raised should have been suitability dealt with. See table below. | Sportsafe carried out an annual inspection of the playground equipment on 2.9.24. The playground equipment was also inspected, by Sportsafe who carried this service out on 2.9.24. |

| Contractors | What we found during the audit |
|--|---|
| The school uses some contractors that have not come from an approved list. Care should be taken to ensure that contractors meet certain criteria including: • what experience they have in the type of work you want done. • what their health and safety policies and practices are • examples of their recent health and safety performance (number of accidents etc.) • qualifications and skills • their selection procedure for sub-contractors • their safety method statements. • health and safety training and supervision • their arrangements for consulting their workforce. • if they have any independent assessment of their competence • if they are members of a relevant trade or professional body. | The school use SMBC's accredited facilities management company Robertson's for their servicing of equipment throughout the site. Contractors are checked by Robertson's. The school were advised to ask for copies of any method statements and risk assessments when jobs such as roofing works are to be undertaken by contractors. |

The school can then decide how much evidence needs to be sought in support of what prospective contractors have stated.

| Pedestrian and Vehicular Movement | What we found during the audit |
|--|--|
| The school should look carefully at arrangements for drop off and pick up times and conduct a whole site-specific risk assessment where high risks are identified, and reactive measures taken to mitigate risk. | |
| Pedestrian walkways should be provided and clearly defined to ensure staff, pupils, parents, and visitors have a safe route into and out of the school building wherever possible. | The Car Park Risk Assessment was dated 2024. |
| Pupil areas should be properly separated from car parks and other vehicle movement areas such as deliveries and refuse collection where practicable. | |

| Kitchen: Access | What we found during the audit |
|---|---|
| Because this is a high-risk area access to the kitchen should be secure and appropriate signage displayed to prevent unauthorised access. | Staff wear the appropriate PPE |
| Any staff or visitors entering the food preparation area should wear appropriate Personal Protective Equipment such as slip resistant footwear. | when working in the kitchen. A sign was in place advising that only authorised personnel could |
| Hair must be tied back and covered with a hat to avoid contaminating food. | access this area. |

| Kitchen: Extractor Hoods | What we found during the audit |
|---|--|
| The extractor hoods should be cleaned and serviced on an annual basis, which is good practice. The school should ensure that the recommended system is cleaned and serviced to the standard in TR19 guidance. | The Kitchen extractor hoods were last serviced on 13.2.24. |
| The last deep clean and ventilation servicing was undertaken on 13.2.24. | |
| BEST PRACTICE: | |

Extractor hoods and local exhaust ventilation systems should be cleaned and serviced by a competent person at least annually.

| Stage Lighting and Rigging | What we found during the audit |
|--|---|
| Stage lighting electrical systems should be periodically inspected annually and have an Electrical Installation Condition Report (EICR) to demonstrate a compliant maintenance regime. Compliance with wiring regulations BS7671: 2008 is required and overhead static equipment such as fixed lighting bars, curtain tracks or other equipment must be inspected annually under the | There is no stage lighting in place at this site. |

Provision and Use of Work Equipment Regulations 1998 (PUWER). Whilst Winched systems such as scenery bars and pulleys need to be tested annually under the Lifting Operations and Lifting Equipment Regulations 1998. PAT is also required annually of frequently moved lights/fittings. See table below.

Roller Shutters

Design, manufacture, supply, and installation of roller shutters comes under Supply of Machinery (Safety) Regulations 2008 but there is no specific health and safety legal requirement dictating how often roller doors should be inspected or tested. SMBC recommends an annual safety and maintenance inspection under PUWER (1998) which requires that work equipment is safe to use on installation and maintained in safe condition for use. Also, regulation 5 of the Workplace (Health, Safety and Welfare Regulations),1992 states that any powered door needs to be "maintained in an efficient state...subject to a suitable system of maintenance". See table below.

What we found during the audit

The last roller shutter service was carried out on 7.2.24 by Door Care and Security.

The roller shutters benefit from a weekly visual inspection by the site team and staff who work in areas where roller shutters are present.

BEST PRACTICE:

BS standard EN 12635:2002 provides guidance on documentation, operation, use and maintenance including requirements for a logbook which should detail; operating instructions, maintenance and repair visits, details of work undertaken, details of changes/upgrades, name date and signature of responsible person

Gates and Barriers

The legal position is that powered gate systems are "machinery". The Health and Safety Executive has lead responsibility for enforcement of this legislation, which has been transposed into UK law as the Supply of Machinery (Safety) Regulations .2008. The school should have suitable and sufficient gates and barriers providing adequate security for the school. All gates should be tested annually by a competent contractor:

What we found during the audit

The last documented gates and barriers service was undertaken by Triad on 14.2.24.

The school also carry out weekly checks of the gates and barriers. The last documented date was 8.10.24.

BEST PRACTICE:

Gates and fences in a primary school should as a minimum conform to BS EN 1176 and be RoSPA approved.

Air Conditioning Units

The school should have an annual maintenance regime in place with a registered air conditioning company. A full record of inspections and maintenance visits should be kept and available for inspection Units should be serviced annually.

The school must check that units have been cleaned and serviced thoroughly.

What we found during the audit

The last air conditioning service was carried out on 30.8.24 by Coolair.

Visual inspections of the units are carried out on a regular basis by the site team and any defects recorded through the appropriate portal.

BEST PRACTICE:

Regular servicing improves the efficiency of your air conditioner. Professional advice says that for every year of operation in which you do not service your air-conditioning it loses 5% of its efficiency. By law any cooling or heating systems with more than 3kg of ozone depleting substances including HCFCs and HFCs must be checked annually for leakage. F-Gas Regulations contain requirements for labelling, leak checking, record-keeping, and maintenance staff qualifications. All air conditioning systems with an effective combined rated output of more

than 12kw must be regularly inspected by an energy assessor. The inspections must be no more than five years apart.

| LOLER Inspections | What we found during the audit |
|---|--|
| All lifting equipment within the school should be tested in line with the legislation every 6 months for equipment used for lifting of persons and 12 months for lifting equipment used for lifting of goods. | The changing bed was last serviced on 2.7.24 by Astor Bannerman (Medical) Ltd. |
| A record should be kept of these tests. | |

WHAT THE LAW SAYS:

Lifting equipment within a school that lifts people including passenger lifts and hoists mechanical needs to be tested every 6 months as do lifting accessories, including slings, shackles, hooks, and chains. The inspected and testing is a requirement of the Lifting Operations and Lifting Regulations, 1998.

10.3 High Risk Curriculum Areas and Staff Training

| Science | What we found during the audit |
|--|-------------------------------------|
| A full range of risk assessments must be in place and the department should comply with all CLEAPS requirements. Full guidance documents are available from HRSafety&HealthTeam@stockport.gov.uk | Not applicable to primary settings. |

| Physical Education: Equipment | What we found during the audit |
|--|--------------------------------|
| All PE equipment should be serviced annually by a | |
| competent person and recommendations made to rectify | Sportsafe last inspected the |
| faults followed up. Service records should be available to | equipment on 2.9.24. |
| evidence this. | |

| Physical Education: Storage | What we found during the audit |
|---|--|
| PE equipment must be properly stored so that staff and pupils can easily access it without causing injury. Mats | PE Equipment was stored in an appropriate way with all areas being |
| must be stored appropriately and away from fire exits. | easily accessible to retrieve |
| Heavy equipment should be stored at lower levels. | equipment in a safe way. |

| Design and Technology | What we found during the audit |
|--|--|
| A full range of risk assessments must be in place and the department complies with all Design and Technology codes of best practice. | In the future the school are looking at providing a small design and technology area for children to learn about woodwork, construction etc. Risk Assessments will be undertaken prior to any areas being operational. |
| BEST PRACTICE: | |

It is recommended by SMBC that all CLEAPS documentation is read and understood by appropriate Heads of Department.

Health and Safety Training: Induction Training

New staff must receive health and safety information during their induction period. Induction training includes procedures for emergency evacuation, a copy of or access to the school's health, safety and wellbeing policy, accident reporting procedure, location of asbestos containing material, how to report maintenance issues, etc.

A formal record of the information given should be placed on staff's personal records.

Further guidance and information on what should be included in the training can be obtained from SLA Online.

What we found during the audit

An appropriate Induction process is in place, where staff sign to say that they have received, read, and understand their induction.

A Staff handbook is in place.

All new staff receive a walk around of the whole school building.

New staff are provided with appropriate training to their job role.

WHAT THE LAW SAYS:

It is a legal requirement that all new staff receive health and safety induction training. Keeping induction training records enables the school to demonstrate that health and safety training has been given. It is recommended that a record of the health and safety induction information given be kept on employees' personal files.

The Health and Safety at Work Act 1974, Section 2 (2) (c)

'Without prejudice to the generality of an employer's duty under the preceding subsection, the matters to which that duty extends include in particular—...

...The provision of such information, instruction, training, and supervision as is necessary to ensure, so far as is reasonably practicable, the health and safety at work of his employees...'

The Management of Health and Safety at Work Regulations 1999, Regulation 10 'Every employer shall provide his employees with comprehensible and relevant information.'

The Management of Health and Safety at Work Regulations 1999, Regulation 13 (2) 'Every employer shall ensure that his employees are provided with adequate health and safety training...on their being recruited into the employer's undertaking; and on their being exposed to new or increased risks..."

General health and safety training

All staff must have received health and safety training relative to their role and responsibility, and this should be recorded in a training matrix and kept up to date by the School Business Manager/Training Coordinator.

It is recommended that those dealing with health safety and wellbeing in schools receive training undertaken by IOSH called Managing Safely:

https://www.iosh.co.uk/managingsafely/#

What we found during the audit

Key staff have received appropriate training in general health and safety, along with, Asbestos Awareness and Legionella Awareness Training. The site manager has attended the SMBC Site Manager Training. The other member of the site team is attending the SMBC Site Manager Training in November 2024.

Basic health and safety training is available on the SMBC Learning Pool.

BEST PRACTICE:

IOSH Managing safely in schools: https://www.iosh.com/training-and-skills/iosh-training-courses/managing-safely/

The Health and Safety at Work Act requires employers to "provide whatever information, instruction, training, and supervision as is necessary to ensure, so far as is reasonably practicable, the health and safety at work of your employees."

This is expanded by the Management of Health and Safety at Work Regulations, which identify situations where health and safety training is particularly important, e.g., when people start work; because of being transferred or given a change of responsibilities; the introduction of new work equipment or a change to existing work equipment; and or where existing skills may have become rusty or need updating.

You should assess the risks to employees while they are at work and to any other people who may be affected by the way the work is carried out. This will identify the required information, instruction, or training required to enable employees to carry out their work safely. Refresher training should also be provided as necessary.

WHAT THE LAW SAYS:

Appropriate training may include but are not limited to the following:

Course:

Fire safety awareness
Fire warden training
Working with hazardous substances

Working with hazardous substances Moving and handling of pupils Ladder / access equipment Requirement of:

Regulatory Reform (Fire Safety) Order Regulatory Reform (Fire Safety) Order

CoSHH Regulations

Manual Handling Regulations
Working at Height Regulations

Attendees Leadership Team

All staff.

Site Supervisor/Cleaners Site Supervisor/Cleaners Site Supervisors

10.4 Performance Monitoring and Measurement

| Active Monitoring | What we found during the audit |
|--|---|
| Monitoring of the working environment and review of work systems, premises, plant, and equipment should be frequent and systematic. | Active monitoring is in place through robust systems. All systems are reviewed on an annual basis. |
| The school should undertake health and safety walk around with the Health and Safety Governor, every term, which is attended by key people. A record should be kept of this walk around and an action plan drawn up and worked through in a prioritised fashion. | The Headteacher and School Health and Safety Officer conduct monthly tours throughout the year. A daily walk around of the site also takes place by SLT. The last documented Health and Safety Governor Tour was undertaken on the 21.8.24. Health and Safety is an agenda item in the weekly staff meeting. The last health and safety meeting took place on 24.9.24. |

WHAT THE LAW SAYS:

The Management of Health and Safety at Work Regulations 1999, Regulation 5

- '(1) Every employer shall make and give effect to such arrangements as are appropriate, having regard to the nature of his activities and the size of his undertaking, for the effective planning, auditee, control, monitoring and review of the preventive and protective measures.
- (2) Where the employer employs five or more employees, they shall record the arrangements referred to in paragraph (1).'

| Reactive Monitoring | What we found during the audit |
|---|---|
| Investigations should be conducted for all accidents and incidents. They should be proportionate to the event and look to identify root cause and corrective actions. NB: The school must contact the Health, Safety and Wellbeing Team in the event of a serious on-site accident and the team will offer support and may conduct an accident investigation. | Investigations are carried out for any serious accidents, and ways of preventing recurrence are discussed at meetings. The school report to SMBC any accidents/incidents via the on-line reporting portal. |
| WHAT THE LAW SAYS: | |

The Social Security (Claims and Payments) Regulations 1979, Regulations 25 (1)

'Every employer shall take reasonable steps to investigate the circumstances of every accident of which notice is given to him...'

10.5 Audit

| Iternal safety tours take place at ast twice a year. A daily walk round of the site is conducted by LT. |
|---|
| • |
| |
| MBC Auditors carry out an annual ealth and safety audit and a report sent to the school within 14 days. |
| |
| 98 |

regard to the nature of his activities and the size of his undertaking, for the effective planning, auditing, control, monitoring, and review of the preventive and protective measures.

Management reviews should be systematically undertaken by the Head teacher and School Business Manager. They should consider Health, Safety, and Wellbeing performance indicators such as number of accidents, location of accidents and trend analysis. There should also be evidence that audit findings, School improvement plans, are reviewed and prioritised by the Head teacher and Board of Governors.

10.6 Statutory Compliance Checklist

| Compliance Activities Within: School Name | | | | | | | |
|---|---|-------------|-----------------|-----------------|--|-----|--|
| Responsible Person | Activity | Frequency | Planned Date | Complete d Date | Completed by (Name of contractor/ site supervisor) | RAG | Notes |
| Contractor | Air Conditioning Service | Annually | | 30.9.24. | Coolair | | |
| Headteacher | Asbestos management - annual management report | Annually | | 2024. | | | |
| Contractor | Asbestos management - specific surveys prior to intrusive works | As required | | | | | As and when required. |
| Contractor | Asbestos Audit Report | Annually | | 3.10.24. | M. Hall – Robertson's | | |
| Contactor | COSHH risk assessments from data sheets | Annually | | July 2024. | J. Preston | | COSHH Assessments to be carried out for washing up liquid and any hand creams in future, due to staff possibly being allergic to ingredients within these items. |
| Contractor | Drainage maintenance | Annually | | | | | Drainage has recently been upgraded. |
| Contractor | Electrical - 5-year fixed wire testing | 5 years | | Summer 2022. | | | The school has recently within 2024 had a full re-wire. |
| Contractor | Electrical - PAT (high risk items only) | Annually | | 9.2.24. | Bradbell | | |
| Site Manager | Electrical - PAT (recorded visual checks of low-risk items) | Bi-annual | | 8.10.24. | Site Team | | |
| Contractor | Fire Risk Assessment | 4 years | | 28.5.24. | Firesec | | Or maybe required if significant changes occur to building layout |
| Contractor | Fire call points | Annually | | 5.6.24. | Firequeen | | |
| Site Manager | Fire call points | Weekly | | 8.10.24. | J. Preston | | |
| Headteacher | Fire drills | Termly | | 17.9.24. | Headteacher | | |
| Contractor | Fire emergency alarm panel | Annually | | 5.6.24. | Firequeen | | The next service has been booked in for |
| Site Manager | Fire emergency alarm panel visual checks | Weekly | | 8.10.24. | J. Preston | | |

| Compliance Activities Within: School Name | | | | | | | |
|---|--|-----------------|-----------------|-----------------|--|-----|--|
| Responsible Person | Activity | Frequency | Planned Date | Complete d Date | Completed by (Name of contractor/ site supervisor) | RAG | Notes |
| Site Manager | Fire emergency lighting visual inspection | Weekly | | 8.10.24. | J. Preston | | |
| Contractor | Fire emergency lighting | Bi-annual | | 5.6.24. | Firequeen | | |
| Site Manager | Firefighting equipment | Weekly | | 8.10.24. | J. Preston | | |
| Contractor | Firefighting equipment | Annually | | 15.1.24. | Firequeen | | |
| Site Manager | Fire means of escape | Weekly | | 8.10.24. | J. Preston | | |
| Contractor | Gas safety - all gas appliances located on site | Annually | | 1.2.24. | Dodd Group | | |
| Contractor | Gas safety - boilers & heating plant comprehensive maintenance | Annually | | 28.6.24. | Dodd Group | | |
| Contractor | Gas safety - pressure systems (insurance check) | Annually | | | | | The school to request this off their facilities management, if required. |
| Contractor | Gas safety - soundness/tightness | 5 years | | 11.10.23. | Dodd Group | | |
| Contractor | Gates and barriers | Annually | | 14.2.24. | Triad | | |
| Site Manager | Gates and barriers | Weekly | | 8.10.24. | J. Preston | | |
| Contractor | Grounds Maintenance | Termly | | August 2024. | | | |
| SLT | Health and Safety Internal Tour | Quarterly | | 21.8.24. | SLT | | |
| SLT | Health and Safety Meetings | Termly | | 24.9.24. | SLT | | |
| SLT | Health and Safety Policy | Every 2-3 years | | Sept 2023. | SLT and the Governing Board | | Policy is reviewed on an annual basis. |
| SLT | Health and Safety Pre-Audit Meeting | Annually | | 7.10.24. | SLT | | This is very good practice. |

| Compliance Activities Within: School Name | | | | | | | |
|---|--|------------|-----------------|-----------------|--|-----|--|
| Responsible Person | Activity | Frequency | Planned Date | Complete d Date | Completed by (Name of contractor/ site supervisor) | RAG | Notes |
| Contractor | Intruder Alarm | Annually | | 18.12.23. | Arnage | | |
| Contractor | Kitchen Appliances Service | Annually | | 1.2.24. | Dodd Group1 | | |
| Contractor | Kitchen deep clean and LEV ventilation service | Annually | | 13.2.24. | Pro-clean | | |
| Contractor | Kitchen Extractor Hoods | Annually | | 1.2.24. | Dodd Group | | |
| Contractor | Legionella - up to date risk assessment and written scheme | Biennially | | 20.10.23. | Acorn Environment | | |
| Contractor | Legionella anti scald | Monthly | | 18.9.24. | Acorn Environment | | |
| Site Supervisor | Legionella management weekly flushing of little used outlets & Temp checks | Weekly | | 8.10.24. | J. Preston | | |
| Headteacher | Lockdown - test of procedures and policy | Bi-annual | 15.10.24. | Dec 2023 | Headteacher | | The next lockdown test is planned for 15.10.24. |
| Contractor | LOLER Equipment – Changing Bed | Annually | | 2.7.24. | Astor Bannerman (Medical) Ltd | | 6 monthly inspections take place relating to this equipment. |
| Contractor | PE Equipment | Annually | | 3.5.24. | Sportsafe | | |
| Contractor | Pest Control | Annually | | 11.9.24. | SMBC | | Pest Control come out at other times too when required. |
| Site Manager | Playground equipment | Weekly | | 8.10.24. | J. Preston | | |
| Contractor | Playground equipment | Annually | | 2.9.24. | Sportsafe | | |
| Site Manager | Premises Checklist updates | Monthly | | 3.10.24. | J. Preston | | |
| Contractor | Roller shutters annual maintenance | Annually | | 7.2.24. | Door Care and Security | | |
| Headteacher | Site Specific Risk assessments - 3 examples | Annually | | Feb 2024. | SLT | | |
| Contractor | Stage lighting and rigging & AV Systems | Annually | | | | | Not applicable to this site. |

| Compliance Activities Within: School Name | | | | | | | |
|---|------------------|----------------------|-----------------|-----------------|--|-----|---------------------------------|
| Responsible Person | Activity | Frequency | Planned Date | Complete d Date | Completed by (Name of contractor/ site supervisor) | RAG | Notes |
| Contractor | Tree inspections | Biennially | | 6.1.23. | Andrew Lawson | | Tree branches cut back in 2024. |
| Contractor | Waste Disposal | As and when required | | 31.7.24. | | | |

10.7 Physical Inspection – Observations and Recommendations

| | Location | Defect | Remedy | Time Frame |
|---|-------------|--------|--------|---------------|
| 1 | None noted. | | | |

10. Guidance to school

On reviewing this audit and inspection report, the Head teacher should report to the appropriate committee, which can in-turn report to the school's governing body.

Referencing the recommendations, the school's leadership team should put together a prioritised action plan to rectify the identified deficiencies. The plan should set out clear actions, identify task completers and associate target timescales.

Support and guidance are available from the Council's Health, Safety and Wellbeing team where needed. HRSafety&HealthTeam@stockport.gov.uk

11. Executive Summary

Entry to the school is via a buzzer system. Visitors to the school sign in on an electronic signing in and out system and are issued with photographic ID to wear around the site. The school recently received Outstanding from Ofsted and, this was apparent throughout the audit. Staff feel very well supported by the leadership team and appeared happy in their work. The school is very children-led with, effective engagement from the headteacher by his involvement with the children. All, of the leadership team are involved in a beneficial way, by assisting their staff members in a safe and helpful manner. There is a Health and Safety Officer on site and the Site Manager is currently training to be a teaching assistant and would like to further develop his health and safety knowledge. The Site Manager is also a trained Forest School Teacher.

The school is a very well-presented and well-maintained building; the decoration throughout, both internal and external, is up-to-date and bright. The school benefits from a very large field and allotment area, where children are growing vegetables for consumption on site. All classrooms were well-appointed, spacious, and bright. The children's work was very well showcased through excellent display work. The children were very polite and were listening intently to their teaching staff during the audit. The staff room was a comfortable area for staff to sit and eat in comfort. The staff room housed a health, safety, and wellbeing board, along with a safeguarding board. The Sunshine Area was very bright and inviting. The school had benefitted from refurbishment of significant areas throughout the site including the external astroturf area, Year 2 flooring, along with a new roof, and guttering. Further refurbishment is planned for Phase 3 for a new SEND Area to be erected to further develop the children with SEND within this setting. The plans were shown to the auditor during the audit and looked to be a wonderful learning and supportive resource for the children. The plans include a Dance Studio for the children. Music is very well supported at this school with there being over 70 different forms of Music being learned. The drainage issues have also been addressed since the last audit.

There are Plant Room Procedures in place and, these are displayed on a sheet which is highlighted in red for persons to read and understand. Plant Rooms were very tidy and did not house any flammable products.

The Nursery area was excellently resourced with large exterior and interior space for the children to learn in an effective manner. The children are currently learning Makaton sign language from an external provided in the Speech and Language Department.

There are many intervention areas throughout site which are well appointed so that the children can learn in an effective way without being disturbed.

There is a lovely Religious Education board in place along with a Prayer Room which has very nice resources within it.

Year 6 children had recently received a visit from 4 local magistrates and are taking place in a consent law court room environment in, the near future.

The school have worked very hard on climate issues and are proudly part of the WE CAN 2025 Calendar. This is an excellent achievement by the school as it recognises their hard work in ensuring a sustainable future.

It was clear from the tidiness, general cleanliness, and happiness of the staff and pupils that this was a school that has a very well-developed health, safety, and wellbeing ethos. Strong risk assessments, in place for all activities, and the caretaker was making all statutory required checks, which were well documented. As recognition of the excellent work that the Head, Health and Safety Officer, and Site Team have done to get the school to this level, the auditor suggested that their duties be detailed in full in Section 2 of the Health, Safety, and Wellbeing Policy. For prospective parents of new pupils (who are able, to see the policy via the school's website), this can be seen as a positive indictment that the school is taking the health and safety of staff and pupils seriously. The school currently has a waiting list of children wanting to come in to learn within this school.

The school is making excellent progress in developing its adherence to HSG65, which is the methodology for effective measurement and management of health, safety, and welfare as outlined by the Health and Safety Executive and adopted by SMBC as its own methodology. The fact that governors are completing termly Health and Safety walk rounds, along with SLT undertaking monthly internal safety tours, from which an action plan is developed and, reports ensue to Governor's meetings, means that Health, Safety, and Wellbeing is well and truly on the radar of all those who work at the school and that there is an excellent level of planning and future proofing for the school.

The school is proactive in the management of health and safety defects, and it was noted on the day of the audit that many of the defects identified had already been recorded and repairs arranged with appropriate contractors. Actions from last year's audit had been completed in a timely manner. The site has two defibrillators which are checked on a regular basis. The defibrillators benefit from having adult and children pads in them.

The school procure their servicing contracts through Robertson's Facilities Management, who are checked by SMBC. One of the current issues is that documentation is slow in reaching the school. The auditor will contact Robertson's relating to this issue.

In terms of next steps, the school should continue to maintain its excellent approach to health and safety and use the opportunity of the Health and Safety notice board in the staff room to highlight Health and Safety initiatives being pursued by SMBC and any initiatives that the school is pursuing itself. The audit report could also be uploaded onto the school's website to help promote the excellent achievements made by the school. The lack of serious accidents reported via the SMBC online portal was a good indicator that health and safety were being proactively managed by the whole school.

No physical inspection actions required.

12. Inspection and Audit Action Plan Item Actions required Time Frame Date Completed 1 The Auditor to feedback relating to the issue of the school waiting for long periods for documentation 7 days.